

M Rubinstein & Associates LLC  
21 C Orinda Way, Orinda California, 94563  
Email: [Mike157@aol.com](mailto:Mike157@aol.com)  
[www.mikerubinsteinassociates.com](http://www.mikerubinsteinassociates.com)  
Phone: 925 254 4679  
Fax: 925 254 4965

## 1984 Westwind II

### AIRCRAFT SPECIFICATION

<b>Total Time AirFrame:</b>	5485 hrs.	<b>Engine Type:</b>	Honeywell TFE731
<b>#1 Engine:</b>	5392 hrs		
<b>#2 Engine</b>	5416 hrs.		

### Engines enrolled on MSPGold



**Exterior:** New June 2004 Overall Matterhorn White with Royal Blue and Red accent stripes

**M Rubinstein & Associates LLC**  
21 C Orinda Way, Orinda California, 94563  
Email: [Mike157@aol.com](mailto:Mike157@aol.com)  
[www.mikerubinsteinassociates.com](http://www.mikerubinsteinassociates.com)  
Phone: 925 254 4679  
Fax: 925 254 4965

**INTERIOR:** New in June of 2004 the interior is an eight passenger configuration with 5 Westwind style seats and a 3 place divan completed in tan leather



### **Avionics**

Dual Collins VHF 20A  
Collins APS 80 IFCS  
Collins FDS 80 IFCS  
Collins ADF 60  
MFD 640  
Collins 230/SEL CAL

Dual Collins VIR 30A  
FMS Global GNS 500  
Dual Collins TDR 90  
ADC 87 Digital  
Radar Collins WXR 300 CLR HF  
CVR Fairchild GA 100

### **Maintenance**

On TriMec maintenance system. All recent work c/w at TriMec. C Check due in 20 hours.

Specifications Are Subject To Purchaser Verification, aircraft is offered subject to prior sale and or withdrawal from marketplace