

M Rubinstein & Associates LLC
21 C Orinda Way, Orinda California, 94563
Phone: 925 254 4679
Fax: 925 254 4965
Email: mike@mrubinsteinassociates.com

1999 Citation VII

AIRCRAFT SPECIFICATION

Total Time:	5,875 Hours	Engine Type:	TFE731-4R-2S
Left Engine:	5,139 TT	MPI Interval:	2,500 Hours
Right Engine:	4,661 TT	CZI Interval:	5,000 Hours
APU:	5,630 TT	Engine Program:	MSP Gold (Incl. APU)



EXTERIOR: New Overall Matterhorn White 2008.
Stripes in Black Tan and Maroon in modern scheme.

M Rubinstein & Associates LLC
21 C Orinda Way, Orinda California, 94563
Phone: 925 254 4679
Fax: 925 254 4965
Email: mike@mrubinsteinassociates.com

INTERIOR: New interior in 2008. Overall beige. The passenger seats are medium beige Sienna leather. The headliner and window reveals are light beige fabrics. The lower sidewalls are medium brown textured fabric. The carpet is medium beige cut pile with center aisle accents. The cabinetry is East Indian Laurel wood veneer and the plating is polished gold.

SEATING: Six passenger seats, in a center club configuration, with a forward right-hand side facing seat and an aft belted (externally serviceable) toilet for an eighth passenger. There is a forward left-hand refreshment center, a large forward right-hand closet, executive and slimline tables and an aft vanity with coat closet. There are 110 VAC outlets at seats #6 and #7, a Fax/Data outlet at seat #6 and provisions for video at each pedestal seat.



M Rubinstein & Associates LLC
21 C Orinda Way, Orinda California, 94563
Phone: 925 254 4679
Fax: 925 254 4965
Email: mike@mrubinsteinassociates.com

PRIMARY AVIONICS

Jar Ops 1 ready	Honeywell SPZ 8000 Dual Flight
Directors and Dual Digital Autopilot	5-tube 5x6" EFIS
Honeywell Primus Radios with Dual Comm	Dual Nav
Dual DME	Dual ADF
Dual RMI	Dual Mode S Transponders

ADDITIONAL AVIONICS

Dual Global GNS-XLS Flight Management System	Coltech CSD-714 SELCAL
Honeywell AA-300 Radio Altimeter	KHF-950 HF Communication (Primary)
KHF-950 HF Communication (Provisions Only)(Second)	Traffic Collision Avoidance System (TCAS II)
Mark VII EGPWS with Wind Shear	Global AFIS
Fairchild Cockpit Voice Recorder	Artex Emergency Locator Beacon
AirCell ST3100	P880 Radar in lieu of P870 Radar
FDR	Diversity XPDR

INSTALLED EQUIPMENT

RVSN Capable	Thrust Reversers
Garrett APU	Tall Flood Lights
EROS Oxygen Masks	Instrument Panel Supplemental Glaresheid Lighting
76 Cubic Ft. Oxygen System	Dual 43 amp/hr Batteries
Baggage Heater	Airshow 400
Dual DVD Player	Flood Cooling

Maintenance

On Cescom	Proparts
No Major Damage History	I-V Inspection Jan 08

[Specifications Are Subject To Purchaser Verification, aircraft is offered subject to prior sale and or withdrawal from marketplace](#)